

SUMMARY OF YOUR HOME INSPECTION.


Shaughnessy, Kamloops, BC November 15, 2016

Report No. 1012

www.kamloopsinspections.com

- SUMMARY O
- ROOFING
- EXTERIOR
- STRUCTURE
- ELECTRICAL
- HEATING
- COOLING
- INSULATION
- PLUMBING
- INTERIOR
- APPENDIX
- REFERENCE

Fireplace damper not fixed open



7. Damper in existing fireplace not fixed open



8. Damper in existing fireplace not fixed open